




Roadway Damage

Photo images courtesy Allen Hatheway

The following images display the destruction of small bridge on the former alignment of SR 77, at the edge of subsidence basin above the south ore body in 1965. The other images illustrate the destruction of pavement structure in the old highway alignment.







Roadway Damage from Subsidence at San Manuel Mine

Photo Courtesy of Lou Sanback

